

Trim Cutter Assembly, 4 Flutes


0°	116RT4-0 116RT8-0
----	----------------------

15°	116RT4-15 116RT8-15
-----	------------------------

25°	116RT4-25 116RT8-25
-----	------------------------

Tool no.	D	Shank	α	Category
116RT4-0	7/8"	1/4"	0°	R
116RT8-0	7/8"	1/2"	0°	R
116RT4-15	1"	1/4"	15°	R
116RT8-15	1"	1/2"	15°	R
116RT4-25	1 1/16"	1/4"	25°	R
116RT8-25	1 1/16"	1/2"	25°	R

Replacement Parts: Ball Bearing: BB-22 ; Arbor 1/4" shank: 108R-4 ; Arbor 1/2" shank: 108R-12



Trim Cutters Only, 4 Flutes

Tool no.	D	d	α	B	Category
116R-0	7/8"	5/16"	0°	1/4"	R
116R-15	1"	5/16"	15°	1/4"	R
116R-25	1 1/16"	5/16"	25°	1/4"	R